

NOTES:


1. OPERATION

1. GENTLY LIFT LATCH AT SIDE OF CONNECTOR.
2. SWING COVER OFF OF CONTACTS.
3. SLIDE THE FLEX TAPE INTO THE CONNECTOR PLACING THE EDGE OF THE FLEX TAPE UNDER 2 HOLD DOWN TABS. MAKE SURE THE POLARITY IS MATCHED BETWEEN THE FLEX TAPE AND THE CONNECTOR COVER.
4. FOLD OVER THE COVER AND PRESS IN PLACE UNTIL THE LATCH IS FULLY ENGAGED.

2. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

3. WILL WORK WITH 10mm OR 12mm WIDE FLEX RIBBON.

JKL PART NO.: ZFS-CH144-12I

			METRIC  THIRD ANGLE PROJECTION		DIMENSIONS ARE IN mm (INCHES) TOLERANCE UNLESS OTHERWISE SPECIFIED 1 PL +/- REF. 2 PL +/- REF. ANGLE +/-		JKL COMPONENTS CORPORATION									
							TITLE NO SOLDER 12mm FLEX TAPE INPUT CONNECTOR									
A ADD NOTE 3 RELEASE & CANCEL PL-1206-02			10/8/13 3/5/13		DRAWN BY L. WENGSTROM		APPV'D BY L.R.		DATE 10/8/13		SIZE A		FSCM NO. 55335		DRAWING NO. ZFS-CH144-12I	
REV. NO. DESCRIPTION/ECO NUMBER APPV'D DATE			- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED		SCALE NONE		RELEASED DATE 3/5/13		REVISION DATE 10/8/13		REV. NO. A		SHEET 1 OF 1			