


DRAWING NUMBER SSF-LXH103GD-UC	REV C
-----------------------------------	----------



* $t < 10 \mu s$

OUR MANY YEARS OF EXPERIENCE DATA ACCUMULATION INDICATE THAT SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.

1. SSH-LXH103 HOLDER.
2. SSL-LX3044GD LED.

MS/DK