


卷之三




## OPERATION MANUAL FOR MDF51 SERIES(BACK LIGHT CONNECTOR)


### CONNECTOR INSERTION

1. INSERT THE CONNECTOR WITH THE GUIDE OF THE CONNECTOR ON PCB.
2. PUSH THE "O" MARK IN THE CENTER OF THE CONNECTOR.  
WHEN THE CRIMP SOCKET IS LOCKED, THERE IS A FIRM LOCK FREEING.

NOTE) INSERT THE CONNECTOR COMPLETELY TO THE END.



PROCEDURE 1




PROCEDURE 2


### CONNECTOR WITHDRAWAL

1. PUSH THE LOCK OF THE MATED CRIMP SOCKET AT BOTH SIDES IN THE DIRECTIONS OF THE ARROWS.
2. WITH PUSHING THE LOCK, PULL STRAIGHT UP.

NOTE) PUSH AND UNLOCK THE SOCKET COMPLETELY.



PROCEDURE 1



PROCEDURE 2