

Exploded view diagram of a mechanical assembly. The diagram shows various components and their assembly sequence, indicated by numbered callouts (1 through 63). Key components include a central motor unit, a terminal support structure, and various mounting brackets and fasteners. A detail view at the top right shows the terminal support location with dimensions 0.51 ± 0.5 and $[.020 \pm .020]$, and labels 8 REF and 34 REF.

- * WARNING
ON INSTALLATION, SET WIRE
DISC TO LARGEST WIRE SIZE
SETTING. USE OF SETTINGS
BELOW MIN. REQUIRED CRIMP
HEIGHT SETTING WILL CAUSE
DAMAGE TO CRIMP TOOLING.

