
## **OptiCam® Pre-Polished Cam Fiber Optic Termination Kits**

PHYSICAL INFRASTRUCTURE SYSTEMS

- For termination of all Panduit<sup>®</sup> OptiCam<sup>®</sup> Pre-Polished Connectors
- OptiCam<sup>®</sup> Termination Tool simplifies tooling and termination, and virtually eliminates operator error by providing visual indication of proper termination after the cam step has been completed
- No adhesive or electricity required for termination
- Include installation instructions and stripping templates for all Panduit<sup>®</sup> OptiCam<sup>®</sup> Pre-Polished Connectors; also available on www.panduit.com



For field polish termination kits, refer to SA-NCCB51

## Components for OptiCam<sup>®</sup> Pre-Polished Cam Termination Kits





▲ LASER LIGHT
AVOID DIRECT EYE EXPOSURE
<5mW @ 635nm
CLASS IIIa/3R LASER PRODUCT
Complies with:
IEC/EN 60825-1:2001;
and also with 21 CFR 1040 10 and
1040.11 with Laser Notice No. 50.
AVOID EXPOSURE - Laser Light
is emitted from the aperture below
or the end of the patch cord.

Part Number	Part Description	Std. Pkg. Qty.		ко 
Tools (included in FCAMKIT)				
FKITCASE	Case for fiber termination kits.	1	_	Ra
CST115	Fiber cable jacket stripper.	1	_	
FALC	Alcohol bottle (empty).	1	10	Cal Ra C Mana
FBFSP	Fiber buffer stripper.	1	10	
FSCDVR	Screwdriver.	1	50	
FGLS	Safety glasses.	1	10	
FTWZR	Tweezers.	1	10	Grou Bo
FWBTL	Water bottle (empty).	1	10	
FKS	Fiber Kevlar shears.	1	10	
FWRKMAT	Fiber safe workmat.	1	10	
Tools (included	in FCAMKIT and FIELDKITUPG)			
FJQCVR	Fiber cleaver tool.	1	10	
OCTT	OptiCam <sup>®</sup> Termination Tool; includes batteries, pouch, and two cradles for each OptiCam <sup>®</sup> Connector – LC, SC, and ST (patch cords available separately).	1		Ind
FVFLPC-2.5SMY	Patch cord for all OptiCam <sup>®</sup> 2.5mm ferrule connectors (SC & ST).	1	10	Lab
FVFLPC-1.25SMY	Patch cord for all OptiCam <sup>®</sup> 1.25mm ferrule connectors (LC).	1	10	
	mables (included in FCAMKIT and FCLEANKIT)			Iden
FWP-C	Lint-free wipes.	100	1000	
FSWB-C	Cleaning swabs.	100	1000	
FSTY	Safety stickers for fiber scraps.	1	10	6
PFX-0	Permanent marking pen, fine tip, black ink (one included in each kit).	12	144	Mana
Replacement Pa	rts			Acc
FJQCVRB	Replacement blade for FJQCVR.	1	10	
FSCC	Tool cradles for SC OptiCam <sup>®</sup> Connectors (two per package).	1	_	
FLCC	Tool cradles for LC OptiCam <sup>®</sup> Connectors (two per package).	1	_	1
FSTC	Tool cradles for ST OptiCam <sup>®</sup> Connectors (two per package).	1	—	
For con	vice and technical support, call 866, 405, 6654 (outside the LLS, and Canada, or			

J. Overhead &

A. System

**Overview** 

B. Copper Systems

C.

Fiber

Optic

Systems

D.

Power

Overhead & Underfloor Routing

044 044

K. Surface Raceway

L. Cabinets, Racks & Cable Management

M. Grounding & Bonding

> N. Industrial

0. Labeling & dentification

P. Cable Management Accessories

For service and technical support, call 866-405-6654 (outside the U.S. and Canada, see catalog back cover).