



Main

Accessory / separate part category	Adaptation accessory
Accessory / separate part type	Adaptor
Product compatibility	ATV61HD37N4...HD75N4 ATV61HD37Y...HD90Y ATV71HD18M3X...HD37M3X ATV71HD37N4...HD75N4 ATV71HD37Y...HD90Y
Accessory / separate part destination	Variable speed drive
Range compatibility	Altivar 61 Altivar 71
Product specific application	Substitution of an ATV38HD46N4X by an ATV61HD37N4 Substitution of an ATV38HD54N4X by an ATV61HD45N4 Substitution of an ATV38HD64N4X by an ATV61HD55N4 Substitution of an ATV38HD79N4X by an ATV61HD75N4 Substitution of ATV58HD28M2X...HD46M2X by ATV71HD22M3X...HD37M3X Substitution of an ATV58HD28M2X by an ATV71HD18M3X Substitution of an ATV58HD33M2X by an ATV71HD22M3X Substitution of ATV58HD33N4...HD79N4 by ATV61HD37Y...HD90Y Substitution of ATV58HD33N4...HD79N4 by ATV71HD37Y...HD90Y Substitution of ATV58HD54N4...HD79N4 by ATV71HD37N4...HD55N4 Substitution of ATV58HD54N4...HD79N4 by ATV71HD45N4...HD75N4 Substitution of an ATV38HD46N4 by an ATV61HD37N4 Substitution of an ATV38HD54N4 by an ATV61HD45N4 Substitution of an ATV38HD64N4 by an ATV61HD55N4 Substitution of an ATV38HD79N4 by an ATV61HD75N4

Complementary

Environment

Offer Sustainability

WARNING: This product can expose you to chemicals including:

Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm.

Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm.

For more information go to www.p65warnings.ca.gov

WARNING: This product can expose you to chemicals including:

Lead and lead compounds, which is known to the State of California to cause cancer and birth defects or other reproductive harm.

Bisphenol A (BPA), which is known to the State of California to cause birth defects or other reproductive harm.

For more information go to www.p65warnings.ca.gov

Contractual warranty

Warranty period

18 months

