XY2CE3C010TK





Main

Range of product	Preventa XY2
Product or component type	Latching emergency stop rope pull switch
Device short name	XY2CE
Housing colour	Blue
Overvoltage category	Class I conforming to EN/IEC 61140 Class I conforming to NF C 20-030

Complementary

Without pilot light
1
164.04 ft (50 m)
Zamak
Stainless steel
Without
1 NC +1 NO
Snap action
LH side
Screw clamp terminal 1 x 0.52 x 1.5 mm ²
7.0810.62 lbf.in (0.81.2 N.m)
3 tapped entry Pg 13.5 cable gland
CE
60000 cycles
16.4 ft (5 m)
3 A at 240 V AC-15, A300 conforming to EN/IEC 60947-5-1 appendix A 0.27 A at 250 V DC-13, Q300 conforming to EN/IEC 60947-5-1 appendix A
10 A
500 V (degree of pollution: 3) conforming to EN/IEC 60947-1 300 V (degree of pollution: conforming to UL 508 300 V (degree of pollution: conforming to CSA C22.2 No 14
6 kV conforming to EN/IEC 60947-1
With conforming to EN/IEC 60947-5-1
<= 25 MOhm conforming to NF C 93-050 method A <= 25 MOhm conforming to EN/IEC 60255-7 category 3
10 A by gG cartridge fuse conforming to EN/IEC 60269

Environment

standards	EN/IEC 60947-5-1	
product certifications	CSA	
protective treatment	TC	
ambient air temperature for operation	-13158 °F (-2570 °C)	
ambient air temperature for storage	-40158 °F (-4070 °C)	
vibration resistance	10 gn (f = 10300 Hz) conforming to EN/IEC 60068-2-6	
shock resistance	50 gn 11 ms conforming to EN/IEC 60068-2-27	
IP degree of protection	IP66 conforming to IEC 60529	

Offer Sustainability

Green Premium product	Green Premium product
Compliant - since 0852 - Schneider Electric declaration of conformity	Compliant - since 0852 - Schneider Electric declaration of conformity
Reference not containing SVHC above the threshold	Reference not containing SVHC above the threshold
Available	Available
Need no specific recycling operations	Need no specific recycling operations
WARNING: This product can expose you to chemicals including:	WARNING: This product can expose you to chemicals including:
Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and	e Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and
Di-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm.	eDi-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm.
For more information go to www.p65warnings.ca.gov	For more information go to www.p65warnings.ca.gov

Warranty period	18 months

