



GAGING LIMITS OF INDENTERS

SELECTOR NUMBER	GAGE-INSPECTION	
	±.0001 GO DIA	±.0001 NO GO DIA
1	.0280	.0330
2	.0320	.0370
3	.0360	.0410
4	.0390	.0440
5	.0450	.0500
6	.0520	.0570
7	.0590	.0640
8	.0680	.0730

USE GAGE P/N G125 AT SELECTOR NUMBER 4

UNCONTROLLED DOCUMENT WILL NOT BE UPDATED

DIMENSIONS IN INCHES - UNLESS OTHERWISE SPECIFIED

