



NOTES:

- 1. OPERATION
 - GENTLY LIFT LATCH AT SIDE OF CONNECTOR.
 - 2. SWING COVER OFF OF CONTACTS.
 - 3. SLIDE THE FLEX TAPE INTO THE CONNECTOR PLACING THE EDGE OF THE FLEX TAPE UNDER 2 HOLD DOWN TABS.
 - 4. FOLD OVER THE COVER AND PRESS IN PLACE UNTIL THE LATCH IS FULLY ENGAGED.
- 2. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.

JKL PART NO.: ZCH-143HD-8 I

			METRIC	DIMENSIC IN mm (IN	NCHES)		K		MPON	NENTS CO	ORPORA	TION
	<u> </u>	 	THIRD ANGLE	TOLERANCE OTHERWISE 1 PL +/- 2 PL +/-	SPECIFIED REF.	TITLE	NO S	OLDEF	R 8mm	FLEX TA		1101
			PROJECTION	ANGLE +/- APPV'D BY		SIZE	FSCM NO.				DUD OI	
	RELEASE & CANCEL PL-1409-03	10/10/14			10/10/14		55335			ZCH-143		LOUEET
REV. N∩	DESCRIPTION/ECO	APPV'D	- CAD DRAWING - MANUAL REVISIONS NOT PERMITTED			SCALE		RELEASED DATE 1(0/10/14	REVISION DATE	REV. NO.	1 of 1