

SYMBOL DEFINITION		MISSING SYMBOLS	
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL ○ DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED	15	NO MISSING SYMBOL NUMBER
	LAST NO. USED		
		12	

DWG STATUS				REVISION HISTORY		AUTH	DR	APVD
DATE	STG	REV	N/P	CHG	ZONE			
31JL03	R	E6	-	-		REDRAWN TO PD	244094	RCH
25FE04	R	06	-	-		MATERIAL SPECIFICATION WAS M0661002	251737	ECB
29MR06	R	06	AA	-		DIM #4 AND #5 MOVED (WAS 0.5 & 2X 9.95)	279145	JTZ
15JN06	R	06	AB	-		10.45 +/- .19 / -.15 WAS 10.45	281635	MM

