XE2SP4151B



Main

| Range of product | Preventa Safety detection |
|---------------------------------------|---------------------------|
| Accessory / separate part designation | Snap action contact block |
| Accessory / separate part type | Contact block |
| Accessory / separate part category | Replacement parts |
| Accessory / separate part destination | 2-step switch |
| Contact rank | Second |

Complementary

| Contacts type and composition | 1 NC + 1 NO |
|-------------------------------|-----------------------|
| Product weight | 0.04 lb(US) (0.02 kg) |

Environment

Offer Sustainability

| WARNING: This product can expose you to chemicals including: | WARNING: This product can expose you to chemicals including: | |
|--|--|--|
| Nickel compounds, which is known to the State of California to cause cancer, and | Nickel compounds, which is known to the State of California to cause cancer, and | |
| Di-isodecyl phthalate (DIDP), which is known to the StateDi-isodecyl phthalate (DIDP), which is known to the State of California to cause birth of California to cause birth defects or other reproductive defects or other reproductive harm. | | |
| For more information go to www.p65warnings.ca.gov | For more information go to www.p65warnings.ca.gov | |
| For more information go to www.p65warnings.ca.gov | For more information go to www.p65warnings.ca.gov | |

Contractual warranty

| Warranty period | 18 months | |
|-----------------|-----------|--|