

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION

Part Number:


62201-7800

Status:

Active

Description:

BMTP Repair Fixture



Documents:

RoHS Certificate of Compliance (PDF)

General	
Product Family	Application Tooling
Series	T9999
Comments	See Tooling Specification (PDF) Above
Function	Repair Fixture
Geographic Area	Global
Level of Automation	Manual
More Detailed Tech Information	applicationtooling@molex.com
Product Name	BMTP
Survey	www.molex.com//review/apptool_survey.html
Tool Type	Repair Kit
UPC	800753277892
Material Info	
Reference - Drawing Numbers	
Application Tooling Documents	ATS-622017800

EU RoHS

Compliance Status

Not Reviewed

REACH SVHC

Not Reviewed

Low-Halogen Status

Not Reviewed

China RoHS

Need more information on product environmental compliance?

Email productcompliance@molex.com

For a multiple part number RoHS Certificate of Compliance, [click here](#)

Please visit the [Contact Us](#) section for any non-product compliance questions.

Search Parts in this Series

T9999Series

Use With

106186 BMTP Backplane

PLEASE CHECK WWW.MOLEX.COM FOR LATEST PART INFORMATION